

Franklin Piston Engines

AD/FK-P/4

**Starter Gear/Damper Assembly
P/No 18708 - Inspection**

NK

Applicability: Model 6A-350-C1 and C2 with S/Nos as listed in the Requirement Document.

Requirement: Franklin SB No 112.

Compliance: Within 100 hours time in service after 31 August 1972 and thereafter at intervals not exceeding 100 hours time in service.