

Franklin Piston Engines

AD/FK-P/2

Connecting Rods - Replacement

NK

Applicability: Model 6VS-335, 6V-335, 6V4-200, 6V4-178, 6A-335, 6A4-150 and 6A4-165.

Requirement: Franklin SB No 105.

Compliance: Before installation an aircraft after 15 June 1967.